

Inspection Report

Permit Holder: Pavilion Energy Corp.
Inspection: 2026-1731
Inspection Date: 2026-05-27
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1537HRS.

Access road- No concerns at the time of inspection.

Lease environment- Lease surrounded by swampy water. Observed ducks in water surrounding location.

Lease Equipment: Pumpjack does not appear to be active. Production records indicate well flowed in April 2026 and has flowed 720 hrs in a calendar year, in the past 5 years. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Signage at wellhead has two different locations (See attached). Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor. Building has windows and doors removed.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100010218
Well ID: 06880
Well Name: PAVILION W STODDART 04-35-085-20
Location: DLS: 04-35-085-20

Authorized by BCER