

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-1732
Inspection Date: 2026-05-22
Inspection Outcome: Inspected

Inspection Comment:

Two wellheads only.

Both wells chained and locked.

d-50-J sign compliant.

Gas detector overranged on LEL from both surface casing vents. Last test for both SCV flows is September 2022.

Remnants of Facility on location; two chem tanks, line heater, above ground piping, pilings, remains of containment ring.

Comments:

1. Observation of flow from d-50-J SCV appears to be different than last test results in IRIS. Please re-test in non-frozen conditions (flow and buildup tests) and report results via e-submission and cc linan.zhang@bc-er.ca [linan.zhang@bc-er.ca]
2. Well sign at d-A50-J requires Flammable symbol.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100060980
Well ID: 23098
Well Name: PETRONAS CARIBOU D- 050-J/094-G-07
Location: NTS: D- 050-J/094-G-07

Permit: 100062660
Well ID: 23717
Well Name: PETRONAS CARIBOU D-A050-J/094-G-07
Location: NTS: D-A050-J/094-G-07

Permit: 100060980
Facility ID: 00022955
Facility Name: PETRONAS CARIBOU D-050-J/094-G-07 001
Facility Type: Well Facility
Location: NTS: D- 050-J/094-G-07

Permit: 100064906
Facility ID: 00007710
Facility Name: PETRONAS CARIBOU D-050-J/094-G-07 004
Facility Type: Gas Dehydrator
Location: NTS: D- 050-J/094-G-07

Permit: 100063224
Pipeline Project ID: 000000307
Segment IDs (Location): 1 (From NTS: D- 050-J/094-G-07 To NTS: C- 086-G/094-G-07), 2 (From NTS: D- 050-J/094-G-07 To NTS: C- 086-G/094-G-07), 3 (From NTS: B- 086-G/094-G-07 To NTS: D- 050-J/094-G-07)

Authorized by BCER