

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1733
Inspection Date: 2026-05-26
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment meet current regulations.

Note: One of the cement barriers for A-88-J well broken and off to the side needs replacing and debris removed.

Note: System indicates CNRL set A-88-J well to suspended but records indicate production in 04/26? Site inspection confirms no suspension actions taken (valve handles not isolated, pipeline not isolated). CNRL to confirm current status of well and update system to reflect current well status.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100047401
Well ID: 19229
Well Name: CNRL HZ NOEL A-A088-J/093-P-01
Location: NTS: A-A088-J/093-P-01

Permit: 100047402
Well ID: 19230
Well Name: CNRL HZ NOEL A- 088-J/093-P-01
Location: NTS: A- 088-J/093-P-01

Permit: 100047401
Facility ID: 00021106
Facility Name: CNRL DEEPBASIN A-088-J/093-P-01 001
Facility Type: Well Facility
Location: NTS: A- 088-J/093-P-01

Permit: 100047402
Facility ID: 00021107
Facility Name: CNRL DEEPBASIN A-088-J/093-P-01 002
Facility Type: Well Facility
Location: NTS: A- 088-J/093-P-01



Inspection Number: 2026-1733
Inspection Date: 2026-05-26

Letter ID: L2602456
Letter Date: 2026-06-01

Authorized by BCER