

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1735
Inspection Date: 2026-05-26
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100060650
Well ID: 23004
Well Name: OVV ECOG HZ KELLY A- 046-G/093-P-01
Location: NTS: A- 046-G/093-P-01

Permit: 100060651
Well ID: 23005
Well Name: OVV ECOG HZ KELLY A-A046-G/093-P-01
Location: NTS: A-A046-G/093-P-01

Permit: 100060650
Facility ID: 00022904
Facility Name: OVV DEEPBASIN A-046-G/093-P-01 001
Facility Type: Well Facility
Location: NTS: A- 046-G/093-P-01

Permit: 100060651
Facility ID: 00022905
Facility Name: OVV DEEPBASIN A-046-G/093-P-01 002
Facility Type: Well Facility
Location: NTS: A- 046-G/093-P-01

Authorized by BCER