

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1736
Inspection Date: 2026-05-27
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1605HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: A6-4-86-20 : Well Abandoned. Surface equipment removed from site. Pumpjack still on site. Signage in place on pumpjack.

6-4-86-20-Pump Jack active. ESD appears open. No barricades in place (Low risk). Signage in place. Surface casing vent flow test- No Flow detected from glove test. Greasy substance down body of wellhead & greasy threads on stuffing box connection (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006286
Well ID: 04424
Well Name: CNRL W STODDART 06-04-086-20
Location: DLS: 06-04-086-20

Permit: 100009918
Well ID: 06693
Well Name: CNRL W STODDART A06-04-086-20
Location: DLS: A06-04-086-20



Inspection Number: 2026-1736
Inspection Date: 2026-05-27

Letter ID: L2602459
Letter Date: 2026-06-01

Authorized by BCER