

Inspection Report

Permit Holder: Pavilion Energy Corp.
Inspection: 2026-1737
Inspection Date: 2026-05-27
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1646HRS.

Access road- Road has deep rutted drainage/tire tracks in areas (See attached).

Lease environment-Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Pumpjack Well active. Chain link fence in place. Signage in place. Surface casing vent flow test- Minor, glove filled in approx 1 min (low risk at this time). Personal monitor indicates Carbon Monoxide on approach to engine building. Building entry test- High Carbon monoxide alarm on personal monitor. Note: all building windows are open and door was propped open at time of inspection. Officer was standing up wind of building during time of inspection. Officer called company emergency number at 1707 to inform of high carbon monoxide in building. Officer was informed an operator was dispatched to address issues.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100008509
Well ID: 05843
Well Name: PAVILION S STODDART 16-24-085-20
Location: DLS: 16-24-085-20



Inspection Number: 2026-1737
Inspection Date: 2026-05-27

Letter ID: L2602464
Letter Date: 2026-06-01

Authorized by BCER