

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-1741
Inspection Date: 2026-06-01
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1336HRS.

Access road- Muddy in spots No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure (1 valve handle not chained & locked). Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

Chemical tank and pump on site- No concerns at time of inspection

Note: Southwest area of location appears to be storage area for tanks, buildings, pipes and other various equipment (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006628
Well ID: 04656
Well Name: TOURMALINE MARTIN D- 013-E/094-H-06
Location: NTS: D- 013-E/094-H-06



Inspection Number: 2026-1741
Inspection Date: 2026-06-01

Letter ID: L2602468
Letter Date: 2026-06-01

Authorized by BCER