

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-1745
Inspection Date: 2026-05-28
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1400HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100049624
Well ID: 19927
Well Name: TOURMALINE MARTIN C- 003-E/094-H-06
Location: NTS: C- 003-E/094-H-06

Permit: 100049624
Facility ID: 00021455
Facility Name: TOURMALINE MARTIN C-003-E/094-H-06 001
Facility Type: Well Facility
Location: NTS: C- 003-E/094-H-06



Inspection Number: 2026-1745
Inspection Date: 2026-05-28

Letter ID: L2602473
Letter Date: 2026-06-01

Authorized by BCER