

## Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.  
Inspection: 2026-1746  
Inspection Date: 2026-05-27  
Inspection Outcome: Inspected

### Inspection Comment:

Thank you for putting the pipeline project numbers on your risers. It really helps with our inspections to be able to describe which line we want to emphasize in that inspection.

The line heater and chemical tanks were not active on the day of inspection. The wells that are suspended are properly suspended with the valves being chained and locked and the flow line disconnected.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073800  
Well ID: 27240  
Well Name: COP HZ INGA 16-10-088-23  
Location: DLS: 16-10-088-23

Permit: 100076623  
Well ID: 28548  
Well Name: COP HZ INGA B16-10-088-23  
Location: DLS: B16-10-088-23

---

Authorized by BCER