

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1773
Inspection Date: 2026-05-28
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active pumpjack. No SCVF
- ensure the chemical tank is properly grounded. The small ground wire/cable that comes attached to the tank (zip tied to the tubing line) is not connected to anything on the end of cable, the tank stand sits on wood blocks, and the ground cable clamp on the spout has no ground cable attached.
- Guarding around all equipment.
- lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006538
Well ID: 04589
Well Name: WHITECAP ET AL BOUNDARY 11-21-085-14
Location: DLS: 11-21-085-14

Authorized by BCER