

## Inspection Report

Permit Holder: Canlin Energy Corporation  
Inspection: 2026-1791  
Inspection Date: 2026-05-28  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-wellhead valves chained and locked. Flowlines are disconnected from the wellhead inside of the insulated boxes at the wellhead. All equipment remains in place. No SCVF

-lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100043356  
Well ID: 17786  
Well Name: CANLIN BOUNDARY 13-24-085-14  
Location: DLS: 13-24-085-14

---

Authorized by BCER