

Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-1804
Inspection Date: 2026-06-02
Inspection Outcome: Inspected

Inspection Comment:

Officer Selected inspection of surface equipment on site.

Performed inspection of location at 1107HRS.

Access road- Very wet and muddy in spots No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Pumpjack & Wellhead Suspended. Barricades in place. Signage at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Polish rod still attached to pumpjack (See attached). Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. No issues at the time of inspection.

Chemical tank - No concerns at time of inspection. Secondary containment is approx. 3/4 full of dark fluid.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002175
Well ID: 01637
Well Name: STRATHCONA ET AL WEASEL D- 025-B/094-H-02
Location: NTS: D- 025-B/094-H-02

Permit: 100002175
Facility ID: 00018533
Facility Name: STRATHCONA WEASEL D-025-B/094-H-02 001
Facility Type: Well Facility
Location: NTS: D- 025-B/094-H-02



Inspection Number: 2026-1804
Inspection Date: 2026-06-02

Letter ID: L2602546
Letter Date: 2026-06-03

Authorized by BCER