

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1807
Inspection Date: 2026-06-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1240HRS.

Access road- Vegetation growing on access road. standing water and mud on sections of access road. Officer walked in from 500M due to wet conditions.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Minor Flow detected from glove test Glove filled in approx 1 min.

Building entry test- No alarms on personal monitor. Building out of service.

Note: Minor debris around site (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100005445
Well ID: 03853
Well Name: CNRL OSPREY D- 057-J/094-A-15
Location: NTS: D- 057-J/094-A-15

Permit: 100005445
Facility ID: 00018707
Facility Name: CNRL OSPREY D-057-J/094-A-15 001
Facility Type: Well Facility
Location: NTS: D- 057-J/094-A-15



Inspection Number: 2026-1807
Inspection Date: 2026-06-02

Letter ID: L2602552
Letter Date: 2026-06-03

Authorized by BCER