

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1811  
Inspection Date: 2026-06-02  
Inspection Outcome: Inspected

### Inspection Comment:

Officer selected inspection of surface equipment on site.

Performed inspection of location at 1322HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Pumpjack & Wellhead Suspended. Barricades in place around pumpjack but not around wellhead (Limited risk due to isolated location). Signage (damaged) in place at entrance (See attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Polish rod removed. Surface casing vent flow test- No Flow detected from glove test. Pump jack building wall fallen off (See attached).

Building entry test- No alarms on personal monitor. Building out of service.

Tank Farm-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009035  
Well ID: 06174  
Well Name: CNRL SCURRY OSPREY D- 043-J/094-A-15  
Location: NTS: D- 043-J/094-A-15

Permit: 100010577  
Facility ID: 00000016  
Facility Name: CNRL OSPREY D-043-J/094-A-15 001  
Facility Type: Battery Site  
Location: NTS: D- 043-J/094-A-15



Inspection Number: 2026-1811  
Inspection Date: 2026-06-02

Letter ID: L2602557  
Letter Date: 2026-06-03

---

Authorized by BCER