

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1813
Inspection Date: 2026-06-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Officer Selected inspection of surface equipment on site.

Performed inspection of location at 1422HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place on wellhead. Positive isolation maintained (flow lines removed). Surface casing vent flow test- No Flow detected from glove test.

Pig Station- No concerns at time of inspection. Out of service.

Note: minor debris around wellhead and various YJ pipe on lease (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100014019
Well ID: 08044
Well Name: CNRL OSPREY B- 015-J/094-A-15
Location: NTS: B- 015-J/094-A-15

Permit: 100014243
Pipeline Project ID: 000005658
Segment IDs (Location): 1 (From NTS: A- 029-J/094-A-15 To NTS: B- 015-J/094-A-15), 2 (From NTS: B- 015-J/094-A-15 To NTS: A- 003-J/094-A-15)



Inspection Number: 2026-1813
Inspection Date: 2026-06-02

Letter ID: L2602561
Letter Date: 2026-06-03

Authorized by BCER