

Inspection Report

Permit Holder: Yoho Resources Inc.
Inspection: 2026-1822
Inspection Date: 2026-05-28
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

I met the Yoho Operator who was already on location. Thanks to them for our discussions. Both wells were active.

Observations;

The Fisher Easy Drive dump valves are weeping grease and needs maintenance.
There is some hydrocarbon staining on the ground around the well heads but no active leaks.

The pipeline riser containment bin needs the ground wire to be properly connected

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100104652
Well ID: 35797
Well Name: YOHO HZ INGA B11-24-087-24
Location: DLS: B11-24-087-24

Permit: 100113766
Well ID: 42434
Well Name: YOHO HZ INGA C11-24-087-24
Location: DLS: C11-24-087-24

Permit: 100103458
Facility ID: 00026550
Facility Name: YOHO INGA 11-24-087-24 001
Facility Type: Well Facility
Location: DLS: 11-24-087-24



Inspection Number: 2026-1822
Inspection Date: 2026-05-28

Letter ID: L2602577
Letter Date: 2026-06-03

Authorized by BCER