

Inspection Report

Permit Holder: Pavilion Energy Corp.
Inspection: 2026-1849
Inspection Date: 2026-06-03
Inspection Outcome: Inspected

Inspection Comment:

Inspected site d-83-L/94-A-12 for permit and order conditions. Pumpjack, flare, separator and fluid tanks with scrubber in operation. Daily log of checks missing June 2, red barrel of product placed outside of secondary containment; should be placed within containment. Site is in good repair.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100017691
Well ID: 09376
Well Name: PAVILION BLUEBERRY D- 083-L/094-A-12
Location: NTS: D- 083-L/094-A-12

Permit: 100017691
Facility ID: 00019195
Facility Name: PAVILION BLUEBERRY D-083-L/094-A-12 001
Facility Type: Well Facility
Location: NTS: D- 083-L/094-A-12

Permit: 100018045
Facility ID: 00002253
Facility Name: PAVILION BLUEBERRY D-083-L/094-A-12 002
Facility Type: Battery Site
Location: NTS: D- 083-L/094-A-12

Permit: 100111063
Road Number: 05829
Segment IDs (Location): 001 (From NTS: D- 082-L/094-A-12 To NTS: D- 083-L/094-A-12)

Authorized by BCER