

Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-1851
Inspection Date: 2026-06-04
Inspection Outcome: Inspected

Inspection Comment:

Site 03-06-079-14 was inspected at or about 1130 hours, it was 12, light rain & overcast. The following was included in the inspection:
Access and signage: no concerns
Site: clean, dry with ruts
Wellheads: Bull plugs, SCV, locks, leaks, -no concerns
Meter/separator buildings: locks, leaks, caps, vents, - no concerns
Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100036186
Well ID: 15987
Well Name: ARGRES DAWSON 03-06-079-14
Location: DLS: 03-06-079-14

Permit: 100073326
Well ID: 27182
Well Name: ARGRES HZ DAWSON A03-06-079-14
Location: DLS: A03-06-079-14

Permit: 100073327
Well ID: 27183
Well Name: ARGRES HZ DAWSON B03-06-079-14
Location: DLS: B03-06-079-14

Permit: 100036186
Facility ID: 00020144
Facility Name: ARGRES HERITAGE 03-06-079-14 001
Facility Type: Well Facility
Location: DLS: 03-06-079-14

Permit: 100073326
Facility ID: 00025047
Facility Name: ARCRES HERITAGE 03-06-079-14 003
Facility Type: Well Facility
Location: DLS: 03-06-079-14

Permit: 100073327
Facility ID: 00025048
Facility Name: ARCRES HERITAGE 03-06-079-14 004
Facility Type: Well Facility
Location: DLS: 03-06-079-14

Permit Holder: ARC Resources Ltd.

Authorized by BCER