

Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-1852
Inspection Date: 2026-06-04
Inspection Outcome: Inspected

Inspection Comment:

Site 11-04-079-14 was inspected at or about 1210 hours, it was 12, light rain & overcast. The following was included in the inspection:
Access and signage: main access scoured (photo attached)
Site: ruts and scour, clean & dry
Wellheads: Bull plugs, SCV, locks, leaks, -no concerns
Meter/separator buildings: locks, leaks, caps, vents, - no concerns
Chemical tanks: leaks, grounds, caps, - no concerns
Riser & pig stations: chains, grounds, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040628
Well ID: 17427
Well Name: ARGRES DAWSON 11-04-079-14
Location: DLS: 11-04-079-14

Permit: 100040628
Facility ID: 00020585
Facility Name: ARGRES DAWSONCREEK 11-04-079-14 001
Facility Type: Well Facility
Location: DLS: 11-04-079-14

Permit Holder: ARC Resources Ltd.

Authorized by BCER