

Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-1855
Inspection Date: 2026-06-04
Inspection Outcome: Inspected

Inspection Comment:

Site 09-08-079-14 was inspected at or about 1250 hours, it was 12, light rain & overcast. The following was included in the inspection:
Access and signage: no concerns
Site: clean and dry
Wellheads: Bull plugs, SCV, locks, leaks, -Operator called to site to lock PRESCO on b well, no other concerns
Meter/separator buildings: locks, leaks, caps, vents, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100062964
Well ID: 23824
Well Name: ARGRES HZ DAWSON 09-08-079-14
Location: DLS: 09-08-079-14

Permit: 100063586
Well ID: 23833
Well Name: ARGRES HZ DAWSON A09-08-079-14
Location: DLS: A09-08-079-14

Permit: 100070112
Well ID: 25980
Well Name: ARGRES HZ DAWSON B09-08-079-14
Location: DLS: B09-08-079-14

Permit: 100062964
Facility ID: 00023342
Facility Name: ARGRES HERITAGE 09-08-079-14 001
Facility Type: Well Facility
Location: DLS: 09-08-079-14

Permit: 100063586
Facility ID: 00023349
Facility Name: ARCRES HERITAGE 09-08-079-14 002
Facility Type: Well Facility
Location: DLS: 09-08-079-14

Permit: 100070112
Facility ID: 00024436
Facility Name: ARCRES HERITAGE 09-08-079-14 004
Facility Type: Well Facility
Location: DLS: 09-08-079-14

Permit Holder: ARC Resources Ltd.

Authorized by BCER