

Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-1856
Inspection Date: 2026-06-04
Inspection Outcome: Inspected

Inspection Comment:

Site 10-08-079-14 was inspected at or about 1240 hours, it was 12, light rain & overcast. The following was included in the inspection:
Access and signage: no concerns
Site: clean & dry
Wellheads: Bull plugs, SCV, locks, leaks, -no concerns
Meter/separator buildings: locks, leaks, caps, vents, - Operator attended to orifice plate (see photo), confirmed clean up
Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038602
Well ID: 16672
Well Name: ARGRES DAWSON 10-08-079-14
Location: DLS: 10-08-079-14

Permit: 100068108
Well ID: 25301
Well Name: ARGRES HZ DAWSON B10-08-079-14
Location: DLS: B10-08-079-14

Permit: 100068200
Well ID: 25300
Well Name: ARGRES HZ DAWSON A10-08-079-14
Location: DLS: A10-08-079-14

Permit: 100068108
Facility ID: 00024090
Facility Name: ARGRES HERITAGE 10-08-079-14 001
Facility Type: Well Facility
Location: DLS: 10-08-079-14

Permit: 100068200
Facility ID: 00024089
Facility Name: ARCRES HERITAGE 10-08-079-14 002
Facility Type: Well Facility
Location: DLS: 10-08-079-14

Permit Holder: ARC Resources Ltd.

Authorized by BCER