

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-1859  
Inspection Date: 2026-06-02  
Inspection Outcome: Inspected

**Inspection Comment:**

Access road good, signage is present. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

There are 2 piles of debris consisting of old boards, timbers etc. that need to be removed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100068176  
Well ID: 25277  
Well Name: OVV ECOG KELLY D- 076-G/093-P-01  
Location: NTS: D- 076-G/093-P-01

Permit: 100068176  
Facility ID: 00024079  
Facility Name: OVV KELLY D-076-G/093-P-01 001  
Facility Type: Well Facility  
Location: NTS: D- 076-G/093-P-01

---

Authorized by BCER