

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1863
Inspection Date: 2026-06-02
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100058253
Well ID: 22422
Well Name: OVV ECOG HZ KELLY C- 069-H/093-P-01
Location: NTS: C- 069-H/093-P-01

Permit: 100058254
Well ID: 22423
Well Name: OVV ECOG HZ KELLY C-A069-H/093-P-01
Location: NTS: C-A069-H/093-P-01

Permit: 100062824
Well ID: 23761
Well Name: OVV ECOG HZ KELLY C-B069-H/093-P-01
Location: NTS: C-B069-H/093-P-01

Permit: 100058253
Facility ID: 00022664
Facility Name: OVV DEEPBASIN C-069-H/093-P-01 001
Facility Type: Well Facility
Location: NTS: C- 069-H/093-P-01

Permit: 100058254
Facility ID: 00022665
Facility Name: OVV DEEPBASIN C-069-H/093-P-01 002
Facility Type: Well Facility
Location: NTS: C- 069-H/093-P-01



Permit: 100062824
Facility ID: 00023303
Facility Name: OVV DEEPBASIN C-069-H/093-P-01 003
Facility Type: Well Facility
Location: NTS: C- 069-H/093-P-01

Authorized by BCER