

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-1866  
Inspection Date: 2026-06-03  
Inspection Outcome: Inspected

### Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048597  
Well ID: 19571  
Well Name: OVV ECOG HZ KELLY D- 004-I/093-P-01  
Location: NTS: D- 004-I/093-P-01

Permit: 100048598  
Well ID: 19572  
Well Name: OVV ECOG HZ KELLY D-A004-I/093-P-01  
Location: NTS: D-A004-I/093-P-01

Permit: 100048597  
Facility ID: 00021259  
Facility Name: OVV DEEPBASIN D-004-I/093-P-01 001  
Facility Type: Well Facility  
Location: NTS: D- 004-I/093-P-01

---

Authorized by BCER