

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-1871  
Inspection Date: 2026-06-03  
Inspection Outcome: Inspected

### Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038183  
Well ID: 16385  
Well Name: OVV ECOG HZ KELLY A- 016-I/093-P-01  
Location: NTS: A- 016-I/093-P-01

Permit: 100038187  
Well ID: 16396  
Well Name: OVV ECOG HZ KELLY A-A016-I/093-P-01  
Location: NTS: A-A016-I/093-P-01

Permit: 100038183  
Facility ID: 00020273  
Facility Name: OVV DEEPBASIN A-016-I/093-P-01 001  
Facility Type: Well Facility  
Location: NTS: A- 016-I/093-P-01

---

Authorized by BCER