

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1872
Inspection Date: 2026-06-03
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038290
Well ID: 16390
Well Name: OVV ECOG HZ KELLY A- 036-I/093-P-01
Location: NTS: A- 036-I/093-P-01

Permit: 100038291
Well ID: 16407
Well Name: OVV ECOG HZ KELLY C- 025-I/093-P-01
Location: NTS: C- 025-I/093-P-01

Permit: 100042929
Well ID: 17865
Well Name: OVV ECOG HZ KELLY C-A025-I/093-P-01
Location: NTS: C-A025-I/093-P-01

Permit: 100038290
Facility ID: 00020275
Facility Name: OVV DEEPBASIN A-036-I/093-P-01 001
Facility Type: Well Facility
Location: NTS: A- 036-I/093-P-01

Authorized by BCER