

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1873
Inspection Date: 2026-06-03
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment meet current regulations.

Note: C-7-I well sign denotes the sh and bh locations are identical. This may be true I am just looking for Ovintiv to confirm.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038185
Well ID: 16392
Well Name: OVV ECOG HZ KELLY C- 007-I/093-P-01
Location: NTS: C- 007-I/093-P-01

Permit: 100038189
Well ID: 16408
Well Name: OVV ECOG HZ KELLY A- 018-I/093-P-01
Location: NTS: A- 018-I/093-P-01

Permit: 100038189
Facility ID: 00020280
Facility Name: OVV DEEPBASIN A-018-I/093-P-01 001
Facility Type: Well Facility
Location: NTS: A- 018-I/093-P-01

Authorized by BCER