

## Inspection Report

Permit Holder: NTE Energy Canada Ltd.  
Inspection: 2026-1884  
Inspection Date: 2026-06-05  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

June 5, 2026 - 10:16 hrs.

Project: 000018223, Segment: 1  
Operator: NTE ENERGY CANADA LTD.  
Status: ACTIVE status.

Flowlines control valves were observed in the open position: minor incidence of snake wrap detaching from flowline (monitoring required).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055781  
Pipeline Project ID: 000018223  
Segment IDs (Location): 1 (From NTS: B- 038-A/094-I-13 To NTS: B- 030-A/094-I-13)

---

Authorized by BCER