

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1887
Inspection Date: 2026-06-04
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100037785
Well ID: 16270
Well Name: OVV ECOG HZ KELLY C- 009-I/093-P-01
Location: NTS: C- 009-I/093-P-01

Permit: 100037786
Well ID: 16271
Well Name: OVV ECOG HZ KELLY C-A009-I/093-P-01
Location: NTS: C-A009-I/093-P-01

Permit: 100037785
Facility ID: 00020237
Facility Name: OVV DEEPBASIN C-009-I/093-P-01 001
Facility Type: Well Facility
Location: NTS: C- 009-I/093-P-01

Permit: 100037786
Facility ID: 00020238
Facility Name: OVV DEEPBASIN C-009-I/093-P-01 002
Facility Type: Well Facility
Location: NTS: C- 009-I/093-P-01

Authorized by BCER