

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-1891
Inspection Date: 2026-06-03
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Noted large cloud of black smoke issuing from flare on plant site a-18-D/94-A-13. Discussed with operator on site. VRU had been temporarily shut down, resumed function at time of inspection. Noted flare still emitting black smoke. This issue has been noted several times over several years, and higher level discussions have occurred on possible solutions. Non-compliances have been issued previously. At time of inspection no engineered solution is in place.

Conducted inspection on a-18-D/94-A-13 wellsite. Noted burst plate installed on F well SCV assembly, D well has SCV assembly tied into a containment vessel. Found C well flow line ESD regulator to be constantly venting.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100072946
Well ID: 26894
Well Name: PETRONAS HZ BLUEBERRY A- 018-D/094-A-13
Location: NTS: A- 018-D/094-A-13

Permit: 100106047
Well ID: 37010
Well Name: PETRONAS HZ BLUEBERRY A-A018-D/094-A-13
Location: NTS: A-A018-D/094-A-13

Permit: 100106047
Well ID: 37011
Well Name: PETRONAS HZ BLUEBERRY A-B018-D/094-A-13
Location: NTS: A-B018-D/094-A-13

Permit: 100106047
Well ID: 37012
Well Name: PETRONAS HZ BLUEBERRY A-C018-D/094-A-13
Location: NTS: A-C018-D/094-A-13

Permit: 100106047
Well ID: 37013
Well Name: PETRONAS HZ BLUEBERRY A-D018-D/094-A-13
Location: NTS: A-D018-D/094-A-13

Permit: 100106047
Well ID: 37014
Well Name: PETRONAS HZ BLUEBERRY A-E018-D/094-A-13
Location: NTS: A-E018-D/094-A-13

Permit: 100109381
Well ID: 39548
Well Name: PETRONAS HZ BLUEBERRY A-F018-D/094-A-13
Location: NTS: A-F018-D/094-A-13

Permit: 100109802
Well ID: 39984
Well Name: PETRONAS HZ BLUEBERRY A-G018-D/094-A-13
Location: NTS: A-G018-D/094-A-13

Permit: 100109802
Well ID: 39985
Well Name: PETRONAS HZ BLUEBERRY A-H018-D/094-A-13
Location: NTS: A-H018-D/094-A-13

Permit: 100109802
Well ID: 39986
Well Name: PETRONAS HZ BLUEBERRY A-I018-D/094-A-13
Location: NTS: A-I018-D/094-A-13

Permit: 100109802
Well ID: 39987
Well Name: PETRONAS HZ BLUEBERRY A-J018-D/094-A-13
Location: NTS: A-J018-D/094-A-13

Permit: 100109802
Well ID: 39988
Well Name: PETRONAS HZ BLUEBERRY A-K018-D/094-A-13
Location: NTS: A-K018-D/094-A-13

Permit: 100072946
Facility ID: 00017960
Facility Name: PETRONAS BLUEBERRY A-018-D/094-A-13 001
Facility Type: Well Facility
Location: NTS: A- 018-D/094-A-13

Permit: 100110867
Facility ID: 00027212
Facility Name: PETRONAS BLUEBERRY A-018-D/094-A-13 002
Facility Type: Compressor Dehydrator
Location: NTS: A- 018-D/094-A-13

Permit: 100110867
Facility ID: 00027213
Facility Name: PETRONAS BLUEBERRY A-018-D/094-A-13 003
Facility Type: Water Hub
Location: NTS: A- 018-D/094-A-13

Permit: 100109878
Pipeline Project ID: 000025437
Segment IDs (Location): 1 (From NTS: D- 028-D/094-A-13 To NTS: A- 018-D/094-A-13), 2 (From NTS: D- 028-D/094-A-13 To NTS: A- 018-D/094-A-13), 3 (From NTS: A- 018-D/094-A-13 To NTS: D- 028-D/094-A-13)

Permit: 100112623
Pipeline Project ID: 000025729
Segment IDs (Location): 1 (From NTS: A- 018-D/094-A-13 To NTS: A- 018-D/094-A-13)

Permit: 100072946
Road Number: 01527
Segment IDs (Location): 001 (From NTS: A- 018-D/094-A-13 To NTS: A- 018-D/094-A-13)

Authorized by BCER