

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-1896
Inspection Date: 2026-06-05
Inspection Outcome: Inspected

Inspection Comment:

Routine inspection of site c-91-B/94-G-2. Inspected surface equipment on site and access road. Access road is maintained and in good repair. Well head, chemical tanks and pump, meter run and riser with pig sender in good repair. No Surface Casing Vent flows detected. No non-compliances found at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100062885
Well ID: 23598
Well Name: PETRONAS JULIENNE C- 091-B/094-G-02
Location: NTS: C- 091-B/094-G-02

Permit: 100062885
Facility ID: 00023220
Facility Name: PETRONAS JULIENNECREEK C-091-B/094-G-02 001
Facility Type: Well Facility
Location: NTS: C- 091-B/094-G-02

Permit: 100063814
Pipeline Project ID: 000020866
Segment IDs (Location): 1 (From NTS: C- 091-B/094-G-02 To NTS: B- 087-A/094-G-02)

Permit: 100084100
Road Number: 04079
Segment IDs (Location): 001 (From NTS: B- 100-A/094-G-02 To NTS: C- 091-B/094-G-02)

Authorized by BCER