

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1899
Inspection Date: 2026-06-04
Inspection Outcome: Inspected

Inspection Comment:

- * Travel to OVV HZ SWAN LAKE 12-12-077-15, sign in site orientation.
- * Meet with site supervisors, discuss operations review documents.
- * Discuss Noise Mitigation Plan for the next pad.
- * Conduct site inspection with supervisors. Discuss inspection.
- * No concerns upon completing this inspection.
- * Sign out return to Dawson Creek.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100120634
Well ID: 54915
Well Name: OVV HZ SWAN LAKE G12-12-077-15
Location: DLS: G12-12-077-15

Authorized by BCER