

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-1904
Inspection Date: 2026-06-03
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-there are two hi/low sensing points at the wellhead...one looks to be out of service, and one is tagged as a "pipeline ESD". Neither one has a lock on it. If these are not in use, please label as such.

-active electric pumpjack. No SCVF

-lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000701
Well ID: 00550
Well Name: SABA O&G BOUNDARY 08-26-085-14
Location: DLS: 08-26-085-14

Permit: 100070449
Pipeline Project ID: 000021937
Segment IDs (Location): 1 (From DLS: 08-26-085-14 To DLS: 15-26-085-14)

Permit: 100103387
Pipeline Project ID: 000024607
Segment IDs (Location): 1 (From DLS: 08-26-085-14 To DLS: 15-26-085-14)

Authorized by BCER