

## Inspection Report

Permit Holder: Enercapita Energy Ltd.  
Inspection: 2026-1906  
Inspection Date: 2026-06-03  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-two abandoned wells with piping and piling for the pumpjacks remaining in place.

-lease and access compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100018904  
Well ID: 09858  
Well Name: ENERCAPITA BOUNDARY 01-26-085-14  
Location: DLS: 01-26-085-14

Permit: 100066278  
Well ID: 24644  
Well Name: ENERCAPITA BOUNDARY A01-26-085-14  
Location: DLS: A01-26-085-14

Permit: 100068525  
Facility ID: 00002358  
Facility Name: ENERCAPITA BOUNDARYLAKE 01-26-085-14 002  
Facility Type: Battery Site  
Location: DLS: 01-26-085-14

Permit: 100020674  
Pipeline Project ID: 000007232  
Segment IDs (Location): 1 (From DLS: 01-26-085-14 To DLS: 06-24-085-14)

---

Authorized by BCER