

## Inspection Report

Permit Holder: Saba Oil & Gas Ltd.  
Inspection: 2026-1907  
Inspection Date: 2026-06-03  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

- Electric pumpjack inactive at time of inspection. There is power to electrical box (can hear it) on the pumpjack. No SCVF
- Two ESD's are closed and in "shut in" mode. There is no chain and lock on the wellhead valves and no flowline disconnect from the wellhead. Pumpjack remains connected to the polish rod.
- lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000724  
Well ID: 00573  
Well Name: SABA O&G BOUNDARY 14-26-085-14  
Location: DLS: 14-26-085-14

---

Authorized by BCER