

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-1912
Inspection Date: 2026-06-03
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- wellhead only, valves chained and locked. No SCVF
- the location signage at the beginning of the lease road is compliant but the location signage at the well has no flammable symbol, no location and is lying on the ground.
- there is a gauge with needle valve on top of wellhead that should be removed and bull plugged as per the Guidelines for an inactive/suspended well.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002220
Well ID: 01672
Well Name: SABA O&G BOUNDARY 04-26-085-14
Location: DLS: 04-26-085-14

Permit: 100070406
Pipeline Project ID: 000021921
Segment IDs (Location): 1 (From DLS: 04-26-085-14 To DLS: 06-26-085-14)

Authorized by BCER