

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1917
Inspection Date: 2026-06-09
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-Inactive electric pumpjack disconnected in place. Wellhead valves are chained and locked. Flowline is disconnected from the wellhead.

-No SCVF

-lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100001257
Well ID: 00971
Well Name: WHITECAP ET AL BOUNDARY 14-27-085-14
Location: DLS: 14-27-085-14

Authorized by BCER