

## Inspection Report

Permit Holder: Whitecap Resources Inc.  
Inspection: 2026-1920  
Inspection Date: 2026-06-04  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-Active H2O injection with cover. No SCVF

-the catadyne hood ventline has come apart and is not properly venting outside of building. Please correct.

-lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100002057  
Well ID: 01543  
Well Name: WHITECAP ET AL BOUNDARY 16-28-085-14  
Location: DLS: 16-28-085-14

---

Authorized by BCER