

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1930
Inspection Date: 2026-06-09
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1116HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. Location surrounded by farm field. No erosion sediment or water runoff concerns.

Lease Equipment: Observation Well. No barricades in place (Limited risk due to isolated location). Signage in place at well. Flow lines removed from wellhead.

Valve Handles chained, locked and secure. No Surface casing vent.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006345
Well ID: 04453
Well Name: CNRL ET AL W EAGLE 16-12-085-19
Location: DLS: 16-12-085-19

Authorized by BCER