

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-1933  
Inspection Date: 2026-06-09  
Inspection Outcome: Inspected

### Inspection Comment:

Site 06-18-079-17 was inspected at or about 1110 hours, it was 17 & overcast.

The following was included in the inspection:

Access and signage: no concerns

Site: clean, dry with ruts - gated open this this day

Wellheads: Bull plugs, SCV, locks, leaks, -no concerns

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073285  
Well ID: 27069  
Well Name: OVV CRP HZ SUNRISE 06-18-079-16  
Location: DLS: 06-18-079-16

Permit: 100073286  
Well ID: 27070  
Well Name: OVV CRP HZ SUNRISE A06-18-079-16  
Location: DLS: A06-18-079-16

Permit: 100073285  
Facility ID: 00024980  
Facility Name: OVV HERITAGE 06-18-079-16 001  
Facility Type: Well Facility  
Location: DLS: 06-18-079-16

Permit: 100073286  
Facility ID: 00024981  
Facility Name: OVV HERITAGE 06-18-079-16 002  
Facility Type: Well Facility  
Location: DLS: 06-18-079-16

Permit Holder: Ovintiv Canada ULC



Inspection Number: 2026-1933  
Inspection Date: 2026-06-09

Letter ID: L2602726  
Letter Date: 2026-06-10

---

Authorized by BCER