

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1944
Inspection Date: 2026-06-09
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100039924
Well ID: 16853
Well Name: OVV HZ KELLY D- 007-J/093-P-01
Location: NTS: D- 007-J/093-P-01

Permit: 100060221
Well ID: 22895
Well Name: OVV ECOG HZ KELLY C- 007-J/093-P-01
Location: NTS: C- 007-J/093-P-01

Permit: 100039924
Facility ID: 00020432
Facility Name: OVV DEEPBASIN D-007-J/093-P-01 001
Facility Type: Well Facility
Location: NTS: D- 007-J/093-P-01

Permit: 100060221
Facility ID: 00022849
Facility Name: OVV DEEPBASIN C-007-J/093-P-01 001
Facility Type: Well Facility
Location: NTS: C- 007-J/093-P-01

Authorized by BCER