

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1949
Inspection Date: 2026-06-09
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1217HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Pumpjack & Well appears active. Chain-link fence around location. Signage in place at entrance. Surface casing vent flow test- No Flow detected from glove test. Grease accumulation around stuffing box (See attached).

Chemical tank and pump on site- No concerns at time of inspection

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100007108
Well ID: 05010
Well Name: CNRL ET AL W EAGLE 14-02-085-19
Location: DLS: 14-02-085-19

Authorized by BCER