

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1953
Inspection Date: 2026-06-09
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1231HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Pumpjack & Well appears active. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Chemical tank and pump on site- No concerns at time of inspection

Produced water injector header Building entry test- No alarms on personal monitor. Building out of service.

Test Separator- Building entry test- No alarms on personal monitor. Note- Natural gas vent line venting outside building has bucket underneath collecting unknown sludge like substance (See attached). Vent line is coming off Kimroy valve from separator flowline.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006705
Well ID: 04716
Well Name: CNRL ET AL W EAGLE 08-02-085-19
Location: DLS: 08-02-085-19

Permit: 100010796
Facility ID: 00000383
Facility Name: CNRL EAGLE 08-02-085-19 001
Facility Type: Satellite Battery
Location: DLS: 08-02-085-19

Authorized by BCER