

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1954
Inspection Date: 2026-06-09
Inspection Outcome: Inspected

Inspection Comment:

Site 11-08-079-17 was inspected at or about 1315 hours, it was 21 & sunny. The following was included in the inspection:

Access and signage: no concerns

Site: clean and dry

Wellheads: Bull plugs, SCV, locks, leaks, -no concerns

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

Riser & pig stations: chains, grounds, - no concerns

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100074285
Well ID: 27488
Well Name: OVV CRP HZ SUNRISE 11-08-079-17
Location: DLS: 11-08-079-17

Permit: 100074286
Well ID: 27489
Well Name: OVV CRP HZ SUNRISE A11-08-079-17
Location: DLS: A11-08-079-17

Permit: 100074287
Well ID: 27490
Well Name: OVV CRP HZ SUNRISE B11-08-079-17
Location: DLS: B11-08-079-17

Permit: 100074288
Well ID: 27491
Well Name: OVV CRP HZ SUNRISE C11-08-079-17
Location: DLS: C11-08-079-17

Permit: 100074285
Facility ID: 00018206
Facility Name: OVV SATURN 11-08-079-17 001
Facility Type: Well Facility
Location: DLS: 11-08-079-17



Permit Holder: Ovintiv Canada ULC

Authorized by BCER