

## Inspection Report

Permit Holder: Aduro Resources Ltd.  
Inspection: 2026-1967  
Inspection Date: 2026-06-09  
Inspection Outcome: Inspected

**Inspection Comment:**

Signage no concerns.

Road into lease was blocked by a piece of farm equipment, road is starting to grow in.

SCV no venting observed.

Well not in operation at time of inspection.

All buildings had the doors wide open.

Methanol tank was empty and didn't have secondary containment.

Inhibitor tank was empty and didn't have secondary containment.

All plugs and caps were in place.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100027320  
Well ID: 13050  
Well Name: ADU MONIAS 03-21-081-22  
Location: DLS: 03-21-081-22

---

Authorized by BCER