

Inspection Report

Permit Holder: Shell Canada Limited
Inspection: 2026-1968
Inspection Date: 2026-06-09
Inspection Outcome: Inspected

Inspection Comment:

4-10-80-19

Signage no concerns

SCV no venting observed

Wellhead was chained and locked at time of inspection

Metering cabinet no concerns

Shutdown isolation valve locked

Actuator no concerns

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

Propane tank is bonded to ground

Pigging area no concerns

Sirius chemical injection system no concerns

All plugs and caps are in place

1-9-80-19

Signage no concerns

SCV no venting observed

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

All plugs and caps in place

A1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead is isolated, chained and locked

All plugs and caps in place

B1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead is isolated, chained and locked

All plugs and caps in place

C1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead is isolated, chained and locked

All plugs and caps in place

D1-9-80-19

Signage no concerns

SCV no venting observed

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

All plugs and caps in place

E1-9-80-19

Signage no concerns

SCV no venting observed

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

All plugs and caps in place

F1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead is isolated, chained and locked

All plugs and caps in place

G1-9-80-19

Signage no concerns

SCV no venting observed

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

All plugs and caps in place

2 chemical tanks with secondary containment no concerns

Chemical injection systems no concerns

J1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead chained and locked at time of inspection

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

All plugs and caps in place

K1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead chained and locked at time of inspection

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

All plugs and caps in place

L1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead chained and locked at time of inspection

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concern

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

All plugs and caps in place

No concerns identified at time of site inspection

M1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead chained and locked at time of inspection

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

All plugs and caps in place

N1-9-80-19

Signage no concerns

SCV no venting observed

Wellhead chained and locked at time of inspection

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

All plugs and caps in place

O1-9-80-19

Signage no concerns

SCV no venting observed

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

All plugs and caps in place

P1-9-80-19

Signage no concerns

SCV no venting observed

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

All plugs and caps in place

Q1-9-80-19

Signage no concerns

SCV no venting observed

Shutdown isolation valve locked

Actuator no concerns

Metering cabinet no concerns

Chemical tank with secondary containment no concerns

Chemical injection system no concerns

All plugs and caps in place

Separators no concerns

Fuel gas cabinet no concerns

MCC no concerns

No concerns identified at time of inspection

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100064766

Well ID: 24120

Well Name: SHELL HZ SATURN 04-10-080-19

Location: DLS: 04-10-080-19

Permit: 100076044

Well ID: 28256

Well Name: SHELL ET AL HZ SATURN 01-09-080-19

Location: DLS: 01-09-080-19

Permit: 100076045
Well ID: 28257
Well Name: SHELL ET AL HZ SATURN A01-09-080-19
Location: DLS: A01-09-080-19

Permit: 100076046
Well ID: 28258
Well Name: SHELL ET AL HZ SATURN B01-09-080-19
Location: DLS: B01-09-080-19

Permit: 100076047
Well ID: 28259
Well Name: SHELL ET AL HZ SATURN C01-09-080-19
Location: DLS: C01-09-080-19

Permit: 100076048
Well ID: 28260
Well Name: SHELL ET AL HZ SATURN D01-09-080-19
Location: DLS: D01-09-080-19

Permit: 100076049
Well ID: 28261
Well Name: SHELL ET AL HZ SATURN E01-09-080-19
Location: DLS: E01-09-080-19

Permit: 100076050
Well ID: 28262
Well Name: SHELL ET AL HZ SATURN F01-09-080-19
Location: DLS: F01-09-080-19

Permit: 100076051
Well ID: 28263
Well Name: SHELL ET AL HZ SATURN G01-09-080-19
Location: DLS: G01-09-080-19

Permit: 100076057
Well ID: 28266
Well Name: SHELL ET AL HZ SATURN J01-09-080-19
Location: DLS: J01-09-080-19

Permit: 100076058
Well ID: 28267
Well Name: SHELL ET AL HZ SATURN K01-09-080-19
Location: DLS: K01-09-080-19

Permit: 100076059
Well ID: 28268
Well Name: SHELL ET AL HZ SATURN L01-09-080-19
Location: DLS: L01-09-080-19

Permit: 100076060
Well ID: 28269
Well Name: SHELL ET AL HZ SATURN M01-09-080-19
Location: DLS: M01-09-080-19

Permit: 100076061
Well ID: 28270
Well Name: SHELL ET AL HZ SATURN N01-09-080-19
Location: DLS: N01-09-080-19

Permit: 100076062
Well ID: 28271
Well Name: SHELL ET AL HZ SATURN O01-09-080-19
Location: DLS: O01-09-080-19

Permit: 100076063
Well ID: 28272
Well Name: SHELL ET AL HZ SATURN P01-09-080-19
Location: DLS: P01-09-080-19

Permit: 100076741
Well ID: 28618
Well Name: SHELL ET AL HZ SATURN Q01-09-080-19
Location: DLS: Q01-09-080-19

Permit: 100064766
Facility ID: 00023505
Facility Name: SHELL HERITAGE 04-10-080-19 001
Facility Type: Well Facility
Location: DLS: 04-10-080-19

Permit: 100076044
Facility ID: 00018281
Facility Name: SHELL GROUNDBIRCH 01-09-080-19 001
Facility Type: Well Facility
Location: DLS: 01-09-080-19



Inspection Number: 2026-1968
Inspection Date: 2026-06-09

Letter ID: L2602774
Letter Date: 2026-06-12

Authorized by BCER