

Inspection Report

Permit Holder: VERMILION ENERGY INC.
Inspection: 2026-1977
Inspection Date: 2026-06-11
Inspection Outcome: Inspected

Inspection Comment:

Site 09-33-081-14 was inspected at or about 0940 hours, it was 15 & sunny. The following was included in the inspection:

Access and signage: no concerns

Site: clean and dry

Wellheads: Bull plugs, SCV, locks, leaks, -no concerns

Meter/separator buildings: locks, leaks, caps, vents, - Operator attended to site to address three leaks in the separator building, followed up with photos of fixes.

Chemical tanks: leaks, grounds, caps, - no concerns

Riser: chains, grounds, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100101469
Well ID: 32837
Well Name: VERMILION HZ MICA 09-33-081-14
Location: DLS: 09-33-081-14

Permit: 100113671
Well ID: 42372
Well Name: VERMILION HZ MICA A09-33-081-14
Location: DLS: A09-33-081-14

Permit: 100113671
Well ID: 42373
Well Name: VERMILION HZ MICA B09-33-081-14
Location: DLS: B09-33-081-14

Permit: 100113671
Well ID: 42374
Well Name: VERMILION HZ MICA C09-33-081-14
Location: DLS: C09-33-081-14

Permit: 100113671
Well ID: 42375
Well Name: VERMILION HZ MICA D09-33-081-14
Location: DLS: D09-33-081-14

Permit: 100102536
Facility ID: 00026473
Facility Name: VERMILION MICA 09-33-081-14 002
Facility Type: Well Facility
Location: DLS: 9-33-81-14

Permit: 100113696
Facility ID: 00027376
Facility Name: VERMILION MICA 09-33-081-14 003
Facility Type: Well Facility
Location: DLS: 9-33-81-14

Permit Holder: VERMILION ENERGY INC.

Authorized by BCER