

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1981
Inspection Date: 2026-06-11
Inspection Outcome: Inspected

Inspection Comment:

Site 11-01-081-15 was inspected at or about 1140 hours, it was 15 & sunny. The following was included in the inspection:
Access and signage: no concerns
Site: clean dry
Wellheads: Bull plugs, SCV, locks, leaks, -no concerns
Meter/separator buildings: locks, leaks, caps, vents, - no concerns
Chemical tanks: leaks, grounds, caps, - no concerns
Riser & pig stations: chains, grounds, - NOTE: 2 of 3 pigs have chains hanging, see photos

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006302
Well ID: 04430
Well Name: CNRL ET AL DOE 11-01-081-15
Location: DLS: 11-01-081-15

Permit: 100006302
Facility ID: 00018760
Facility Name: CNRL DOE 11-01-081-15 001
Facility Type: Well Facility
Location: DLS: 11-01-081-15

Permit: 100025126
Facility ID: 00003761
Facility Name: CNRL DOE 11-01-081-15 002
Facility Type: Compressor Dehydrator
Location: DLS: 11-01-081-15

Permit: 100025132
Facility ID: 00000441
Facility Name: CNRL DOE 11-01-081-15 003
Facility Type: Compressor Dehydrator
Location: DLS: 11-01-081-15

Permit Holder: Canadian Natural Resources Limited



Inspection Number: 2026-1981
Inspection Date: 2026-06-11

Letter ID: L2602793
Letter Date: 2026-06-15

Authorized by BCER