

Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-1991
Inspection Date: 2026-06-10
Inspection Outcome: Inspected

Inspection Comment:

Observations;

The pile of broken matting needs to be removed as part of a Spring clean up.
There is also one short length of pipe. All wells were active. Both test separators were compliant in their set up and operation as well as a chemical tank.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100105791
Well ID: 36805
Well Name: ARGRES HZ INGA 02-27-084-24
Location: DLS: 02-27-084-24

Permit: 100107559
Well ID: 38404
Well Name: ARGRES HZ INGA A02-27-084-24
Location: DLS: A02-27-084-24

Permit: 100107559
Well ID: 38405
Well Name: ARGRES HZ INGA B02-27-084-24
Location: DLS: B02-27-084-24

Permit: 100107559
Well ID: 38406
Well Name: ARGRES HZ INGA C02-27-084-24
Location: DLS: C02-27-084-24

Permit: 100107559
Well ID: 38407
Well Name: ARGRES HZ INGA D02-27-084-24
Location: DLS: D02-27-084-24

Permit: 100107559
Well ID: 38408
Well Name: ARGRES HZ INGA E02-27-084-24
Location: DLS: E02-27-084-24

Permit: 100107559
Well ID: 38409
Well Name: ARGRES HZ INGA F02-27-084-24
Location: DLS: F02-27-084-24

Permit: 100107559
Well ID: 38410
Well Name: ARGRES HZ INGA G02-27-084-24
Location: DLS: G02-27-084-24

Permit: 100107559
Well ID: 38411
Well Name: ARGRES HZ INGA H02-27-084-24
Location: DLS: H02-27-084-24

Permit: 100107559
Well ID: 38413
Well Name: ARGRES HZ INGA J02-27-084-24
Location: DLS: J02-27-084-24

Permit: 100107949
Facility ID: 00026962
Facility Name: ARGRES ATTACHIE 02-27-084-24 001
Facility Type: Well Facility
Location: DLS: 02-27-084-24

Authorized by BCER