

Inspection Report

Permit Holder: Yoho Resources Inc.
Inspection: 2026-1995
Inspection Date: 2026-06-11
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

I stopped into the Yoho Resources main plant at approximately km 9.5 on the Inga Lake Rd. Thanks to the 2 operators on shift for our discussions.

Observations;

There is a short piece of discarded crumpled up culvert to remove on the left side of the upper pad access and just inside the tree line. The meter run skid on the lower well pad is weeping grease from the valve stem of the back pressure valve, however, no LELs were detected. All meter runs for the upper and lower well pads are current with their service/calibrations. The line heater is in operation. The propane tank is not in service.

One item to mention is the PSL 1400 supplied with instrument air and the inspector is asking Yoho to check the shutdown key for the site. There is a Swagelok valve on this supplied air line outside the meter skid that may need to be locked in the open position.

There is a chemical tank on the upper pad that is bonded to the frame however the ground wire has been cut and removed. The chemical pump is not operating at this time. Please address.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100075822
Well ID: 28182
Well Name: YOHO INGA 01-19-087-23
Location: DLS: 01-19-087-23

Permit: 100079379
Well ID: 29915
Well Name: YOHO HZ INGA A01-19-087-23
Location: DLS: A01-19-087-23

Permit: 100079380
Well ID: 29916
Well Name: YOHO HZ INGA B01-19-087-23
Location: DLS: B01-19-087-23

Permit: 100105729
Well ID: 36736
Well Name: YOHO HZ INGA C01-19-087-23
Location: DLS: C01-19-087-23

Permit: 100115382
Well ID: 44173
Well Name: YOHO HZ INGA D01-19-087-23
Location: DLS: D01-19-087-23

Permit: 100115382
Well ID: 44174
Well Name: YOHO HZ INGA E01-19-087-23
Location: DLS: E01-19-087-23

Permit: 100115382
Well ID: 44175
Well Name: YOHO HZ INGA F01-19-087-23
Location: DLS: F01-19-087-23

Permit: 100115382
Well ID: 44176
Well Name: YOHO HZ INGA G01-19-087-23
Location: DLS: G01-19-087-23

Permit: 100115382
Well ID: 44177
Well Name: YOHO HZ INGA H01-19-087-23
Location: DLS: H01-19-087-23

Permit: 100115382
Well ID: 44178
Well Name: YOHO HZ INGA I01-19-087-23
Location: DLS: I01-19-087-23

Permit: 100079379
Facility ID: 00026032
Facility Name: YOHO INGA 01-19-087-23 001
Facility Type: Well Facility
Location: DLS: 01-19-087-23

Permit: 100117804
Facility ID: 00027921
Facility Name: YOHO INGA 01-19-087-23 002
Facility Type: Well Facility
Location: DLS: 01-19-087-23

Authorized by BCER